

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BN330
NW
1/2-1
0.534 mi.
2821 ft.

OPPOSITE OF
2522 WEST 16TH ST
BROOKLYN, NY

Site 2 of 2 in cluster BN

NY Spills S111159051
N/A

Relative:
Higher

Actual:
9 ft.

SPILLS:

Name: OPPOSITE OF
Address: 2522 WEST 16TH ST
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 1104595 / 2011-09-01
Facility ID: 1104595
Facility Type: ER
DER Facility ID: 406798
Site ID: 452204
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C4
SWIS: 2401
Spill Date: 2011-07-23
Investigator: RWAUSTIN
Referred To: Not reported
Reported to Dept: 2011-07-23
CID: Not reported
Water Affected: Not reported
Spill Source: Commercial/Industrial
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2011-07-23
Spill Record Last Update: 2011-09-01
Spiller Name: Not reported
Spiller Company: CON ED
Spiller Address: Not reported
Spiller Company: 999
Contact Name: ERT

DEC Memo: "9/1/11 - Austin - Pole transformer leaked 4 gals. onto car and pavement - Con Ed contained and cleaned up the spill - See the documents in eDocs for further info - Case closed - end"

Remarks: "cleanup pending - on sidewalk and vehicle"

All Materials:

Site ID: 452204
Operable Unit ID: 1202381
Operable Unit: 01
Material ID: 2198954
Material Code: 0020A
Material Name: transformer oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 4.00
Units: G
Recovered: Not reported
Oxygenate: Not reported